

Scania R520 A 6x2 NA, Tractor



Scanvo Trucks Danmark A/S
Hårup Skovvej 7, Hårup
8600 Silkeborg

Sælger
Salgsafdeling
salg@scanvo.dk
+45 8724 4370
+45 3046 2148 / 2498 2148 / 2497 2148

Basis		Suspension		Cab	
Type	Tractor Unit	Front, parable	✓	Cab type	CR20 H
Aksel	6x2	Rear, air	✓	Number of sleeper berths	2
Stand	Very fine			Engine cab heater	✓
Registration		Brakes		Radio	✓
Model year	2019	Disc brake	✓	Refrigerator	✓
Reg. date	24-05-2019	ABS	✓	Walkie	✓
Latest inspection	12-06-2024	Retarder	✓	Navigation	✓
Chassis number (VIN)	YS2R6X20005513877	Fahrhaus ausen		Coffee machine	✓
Ref. no.	7260	Color	Chilli Red	Lane-assistent	✓
Engine and transmission		Spoilers	✓	Distance radar	✓
Engine	V8	Lightbox	✓	Multifunction steering wheel	✓
Hp	520	Fog lights	✓	Thermo	✓
Km	378000	Chassis		Air suspension cab	✓
Gear box	GRS905R opticroise aut shift	Wheelbase mm	2950	Automatic air conditioning	✓
EURO type	6	Axle load, front kg	7500	Automatic disaster Brake (FCW)	✓
Number of tanks	1	Axle load, rear kg	19000	Radial bolster	
Litre of tank	610	Closed sides	✓	Make	Jost
Rear axle, single interchange	✓	Aluminium cover	✓	Pneumatic	✓
Ad-blue	✓	Tyres		Height mm	1150
Adblue litre of tank	76	% remaining	50 - 70 - 70	Weight	
Without clutch pedal	✓	Dimensions	385/55R22,5 - 315/60R22,5 - 315/60R22,5	Overall weight kg	26000
Prepared PTO MOTOR	✓	Double boogie	✓	Tare weight kg	9531
				King pin kg	16340

Beskrivelse

Scania R520 A 6x2 NB euro 6 Next Generation !

Pulling - sliding stool - 610 ltr diesel tank - 76 ltr AD Blue tank inside chassis - 24 volt power connector for lift - air barrier taps - chassis skirts - aluminum cover in front of stool -

Opticroise aut gear shift - retarder - parabolic suspension front - rear air suspension - dual mounted bogie - 2950 mm short wheelbase - 2 x LED work lights mounted at bottom of side spoiler

CR20 H cab equipped with: air conditioning - engine/ cabin heater - 2 berths - navigation - air suspended cab - laminate windows - coffee machine in upper cabinet - spoiler set - cab color Chilli Red - appears in nice and regular condition

Continuously serviced at Scania large service performed at / km 358.0241 d. 24/10-2022 oil change on engine, gearbox + rear gear and filters

Contact Scanvo +45 87244370 - or by mail salg@scanvo.dk

Visit our website www.scanvo.dk here you will find more than 300 units of transport equipment



