

Mitsubitsi Fuso CANTER 9C150, Haken



Scanvo Trucks Danmark A/S
Hårup Skovvej 7, Hårup
8600 Silkeborg

Sælger
Salgsafdeling
salg@scanvo.dk
+45 8724 4370
+45 3046 2148 / +45 2498 2148

Basis		Engine and transmission		Chassis	
Type	Truck	Engine	4 cyl.. 3,0	Wheelbase mm	3850
Aksel	4x2	Hp	150	Axle load, front kg	3100
Stand	Fine	Km	224500	Axle load, rear kg	6000
Registration		Gear box	Aut shift	Toolbox	✓
Model year	2017	EURO type	6	Working light	✓
Reg. date	19-06-2017	Number of tanks	1	Suspension	
Reg. no.	AW81858	Litre of tank	xxxx	Front, conventional	✓
Latest inspection	17-07-2023	Ad-blue	✓	Rear, air	✓
Chassis number (VIN)	TYBFECX1GLDY11375	PTO gearbox	✓	Weight	
Ref. no.	7586	Adblue litre of tank	20	Loading capacity kg	4310
Cab		Without clutch pedal	✓	Overall weight kg	8550
Cab type	dag cab	Fahrhaus ausen		Tare weight kg	4240
Air-conditioning	✓	Stickers	✓	Total weight, low loader kg	12050
Mirror camera	✓	Color	Blåmetallic	Hook lift	
Rear-view camera	✓	additional worklights	✓	Make	Hiab
Radio	✓	Blitz lights	✓	Type	XR8S4150 H-I-N med udv. låse
Walkie	✓	Brakes		Load capacity	8
Number of seats 2 mand's passagersæde		Disc brake	✓	Serial number	X85415070236252
Tyres		ABS	✓	Model year	2017
% remaining	80 - 70	Tippers		Removable hook	✓
Dimensions	205/75R17,5	Rear tipper	✓	Max container messure mm	5600
				Last inspection	28/12-2023

Beskrivelse

Mitsubishi Fuso Canter 9C15 Duonic Euro 6

HIAB 8 ton hook lift model XRS4150 - hook tower height 1450 mm - external container locks - length from hook tower to rear bumper 4400 mm = 5100 mm container length, when using a hydraulic extension bumper + 500 mm, it is possible to drive with a container length of approx. 5600 mm - top edge container roll height = 940 mm - tool boxes on the left side - max total height 2300 mm and length 6150 mm - short axle distance so that it can get in where the others give up!

Spec: axle distance 3850 - Aut gearbox - air-suspended rear axle - 2 man passenger seat

Equipment such as: Flash boom - flash light - 2 x pcs. extra work light - reverse + cyclist camera - air-sprung rear axle

Regularly serviced at Mercedes

The car has the possibility of approval for a 3500 kg ball coupling, but is NOT fitted!

Contact Scanvo +45 87244370 - email salg@scanvo.dk

- AN OFFER YOU CAN'T REFUSE

See more exciting topics on our website www.scanvo.dk

Nye og brugte containere
Mere end 100 enheder!





