

## SH 7,5 mtr fast lad containerlase + ramper, Autotransport

**Brakes** 



Scanvo Trucks Danmark A/S Hårup Skovvej 7, Hårup 8600 Silkeborg

Sælger Salgsafdeling salg@scanvo.dk +45 8724 4370 +45 3046 2148 / +45 2498 2148

Registration	
Model year	2009
Reg. date	19-06-2009
Reg. no.	PE7866
Latest inspection	15-11-2024
Chassis number (VIII	N) JH9KAF20809KM1264
Ref. no.	7785
Basis Type	Drawbar
Aksel	2
Stand	Fine
Tyres	
% remaining	40 - 0
Dimensions	245/70R17,5

Drum brakes		
ABS		
Weight		
Loading capacity kg 14960		
Overall weight kg 20000		
Tare weight kg 5040		
King pin kg 1000		
Coupling		
Electrical coupling EBS - 13 polet lysstik		
Air-coupling duromatic		
Manufacturer 57 mm træk øje		
V "KN air" 68		
V "KN no air" 90		
Coupling height mm 500 (kan ændres)		

Suspension	
Air	✓
Chassis	
Toolbox	✓
Wheelbase to 1. axel mm	4625
Total length mm	9150
Working light	<b>√</b>
Shaft type	BPW
Axle load kg	10000 - 10000
Truck body / box	
Bottom	finer
Box type	fast lad

## Beskrivelse

Truck bed height mm

Dimensions

Length mm Width mm

SH 20 ton trailer with 7500 mm fixed bed

 $2 \times 4$  pcs. lowered container locks for 20 foot container - 120 mm edge frame plywood bed base in good condition

7550

2550

900

loose 600 mm removable posts where profile planks can be mounted so that the goods stay inside the bed

57 mm towing eye - coupling length 9150 mm - coupling height is currently 500 mm - can be changed to desired height at additional cost

Included are ALTEC model VFR105 SO aluminum loose ramps length 2300 mm x Width 500 mm weight 45 kg year 2018 - which are located in a magazine box under the bed

transverse litter tray under the bed in front width 700 x Height 350 mm + plastic tool box

Gear support legs front + rear when the trailer is positioned with a load

The loading height is 900 mm - by lowering the air suspension in the rear and raising the towing eye in the front, the loading height in the rear is ONLY 680 mm

BPW axles - drum brakes - air suspension with built-in hanging lowering valve in the box on the left side MXN camera line with plug in front for the front vehicle

Bliz lamps - 2 x 2 pcs. LED work / reverse lights under the bed - LED taillights

In good condition considering the year - I believe the chassis was sandblasted and completely painted about 5 years ago

Contact Scanvo +45 87244370 or email salg@scanvo.dk















































