

Scania R500 XT A 6x4 NB, Tractor



Scanvo Trucks Danmark A/S
Hårup Skovvej 7, Hårup
8600 Silkeborg

Sælger
Salgsafdeling
salg@scanvo.dk
+45 8724 4370
+45 3046 2148 / +45 2498 2148

Basis	
Type	Tractor Unit
Aksel	6x4
Stand	Very fine
Registration	
Model year	2018
Reg. date	26-06-2018
Reg. no.	BY79575
Latest inspection	10-07-2024
Chassis number (VIN)	YS2R6X40002148905
Ref. no.	7865
Engine and transmission	
Engine	DC13 155
Hp	500
Km	552000
Gear box	GRSO905 Opticruise aut shift
EURO type	6
Number of tanks	1
Litre of tank	610
Rear axle, hub reduction	✓
PTO engine	✓
Adblue litre of tank	80
Without clutch pedal	✓
Suspension	
Front, parable	✓
Rear, air	✓

Brakes	
Disc brake	✓
ABS	✓
Engine brake	✓
Fahrhaus ausen	
Warninglight	✓
Color	Yellow
Spoilers	✓
Lightbox	✓
Fog lights	✓
additional worklights	✓
Blitz lights	✓
LED front light	✓
Lamp boom on rear wall	✓
Chassis	
Wheelbase mm	3150
Axle load, front kg	9000
Axle load, rear kg	19000
Hydraulic installation	✓
Closed sides	✓
Hydraulic 2.	✓
Working light	✓
Liftable axles	aflastbar 3. ej løft
Aluminium cover	✓

Cab	
Cab type	CR20 H
Number of sleeper berths	1
Engine cab heater	✓
Radio	✓
Refrigerator	✓
Walkie	✓
Navigation	✓
Lane-assistent	✓
Distance radar	✓
Thermo	✓
Air in cabin for cleaning	✓
Air suspension cab	✓
Automatic air conditioning	✓
Automatic disaster Brake (FCW)	✓
Loading camera	✓
Leather seats	✓
Tyres	
% remaining	80 - 20 - 20
Dimensions	385/65R22,5 - 315/80R22,5 - 315/80R22,5
Radial bolster	
Make	Jost
Pneumatic	✓
Height mm	1220
Weight	
Loading capacity kg	15200
Overall weight kg	26000 / 33000
Tare weight kg	10800
King pin kg	15200
Total weight, low loader kg	80000

Beskrivelse

Scania R500 XT model A 6x4 NB - Block tractors approved for 80 tons
Hydraulic system 2 lines for tipping - chassis skirts - 24 volt power connector for trailer - large aluminum. cover in front of the stool - special toolbox on the right side behind the cab - storage V- trays between the rear axles - 38mm Rocking trailer hitch with light / air and 24 volt power led to the rear

3150 mm axle distance - 9000 front axle - parabolic + air suspension - Opticruise gearbox with aut gearshift + overdrive which gives low engine revs with empty driving - hub reduction rear wheels -

CR20 H cab - 1 berth leather seats - refrigerator - air conditioning - engine Cabin heater - walkie - laminate windows - navigation - radio - LED headlights and LED high beams in the roof + light sign and rotary indicator - Light boom behind the cab with various lights and lights - flash lights in the front grille - loading camera + wide load camera on extension rods via air - engine cover in black - air gun for cleaning in the cab

In very good condition - and serviced by Scania 31/8-2024 km 550,682 gear/rear gear oils changed - 17/2-2024 km 513,125 km engine oil + filters changed











