

# Legras 91,8 m3 - VBK Aut. presenning, Walkingfloor



Scanvo Trucks Danmark A/S  
 Hårup Skovvej 7, Hårup  
 8600 Silkeborg

Sælger  
 Salgsafdeling  
 salg@scanvo.dk  
 +45 8724 4370  
 +45 3046 2148 / +45 2498 2148

Basis		Chassis		Tyres	
Type	Semi-Trailer	Wheelbase mm	1-2=1310 - 2-3=1810	% remaining	100% - 100% - 100%
Aksel	3	Shaft type	BPW	Dimensions	385/65x22,5
Stand	Brand new	Liftable axles	1 aksel	Alloy wheels	✓
Suspension		Axle load kg	Samlet 27000	Registration	
Air	✓	Self steering Axles	3 aksel	Model year	2026
Brakes		Weight		Ref. no.	5124
Drum brakes	✓	Loading capacity kg	35660	Brand new	✓
ABS	✓	Overall weight kg	45000		
		Tare weight kg	9340		
		King pin kg	18000		

## Beskrivelse

Brand new LEGRAS 91.8m3 walkingfloor trailer  
 - VBK automatic tarpaulin

- BPW axles with drum brakes
- Lift axle on axle 1
- Co-steering axle 3
- Central lubrication block for lubrication of steering shaft
- Alcoa DuraBright alloy wheels
- TPMS tire pressure monitoring
- Extra long gooseneck adapted to 3,150mm puller
- Strong 13mm floor
- Hardox wear plate at the rear
- Wireless remote control for floor and roof
- Prepared for floor tarpaulin
- Air outlet at the rear
- Reinforced rear doors with 2 bar closers per door
- Double sealing strip on rear doors
- 6 pcs. LED work lights on the outside
- Position, indicator and brake lights at the top in the back
- 8 pcs. built-in LED side marker lights per page
- Operating valves built into tool boxes
- Electrical junction box built into tool box
- Large plastic tool box for storage
- Broom/forest fittings
- Spare wheel suspension
- Loose aluminum ladder
- 6kg fire extinguisher
- Stool height approx. 1,150 mm
- External height front approx. 4,050 / behind approx. 4,050 mm
- Internal height front approx. 2,700 / behind approx. 2,775 mm
- Chassis colour: RAL7024 Grey
- Case colour: Volvo Champagne 2704BEI Steel Down Metallic

The trailer is also equipped with a temperature sensor to measure the oil temperature, which can deactivate the floor, in case of too hot oil, to prevent overheated oil and burnt gaskets.

See possibly also 4 axle correspondingly in stock.

- AN OFFER YOU CAN'T REFUSE

Contact us for further information on tel. 87254370 or salg@scanvo.dk







